




It's back.




VISIBILITY



PUSHABILITY



TORQUABILITY













Cook Beacon® Tip 5.0 Fr

ANGIOGRAPHIC CATHETERS

ORDERING INFORMATION

Cook Beacon® Tip 5.0 Fr



























ANGIOGRAPHIC CATHETERS

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Tip Configuration	
G08441	HNBR5.0-35-65-P-NS-C1	5.0	.035	65	C1	
G08446	HNBR5.0-38-65-P-NS-C1	5.0	.038	65	C1	
G11203	HNBR5.0-38-80-P-NS-C1	5.0	.038	80	C1	
G08623	HNBR5.0-35-100-P-NS-C1	5.0	.035	100	C1	
G08442	HNBR5.0-35-65-P-NS-C2	5.0	.035	65	C2	
G08447	HNBR5.0-38-65-P-NS-C2	5.0	.038	65	C2	
G11202	HNBR5.0-35-80-P-NS-C2	5.0	.035	80	C2	
G08586	HNBR5.0-38-80-P-NS-C2	5.0	.038	80	C2	
G08796	HNBR5.0-35-100-P-NS-C2	5.0	.035	100	C2	
G13560	HNBR5.0-38-80-P-NS-CHG-B	5.0	.038	80	CHG-B	
G13561	HNBR5.0-38-80-P-NS-CHG-C	5.0	.038	80	CHG-C	
G11430	HNBR5.0-38-80-P-NS-CHG2.5	5.0	.038	80	CHG2.5	
G11414	HNBR5.0-35-65-P-NS-DAV	5.0	.035	65	DAV	
G11435	HNBR5.0-38-65-P-NS-DAV	5.0	.038	65	DAV	
G08699	HNBR5.0-35-100-P-NS-DAV	5.0	.035	100	DAV	
G08581	HNBR5.0-38-100-P-NS-DAV	5.0	.038	100	DAV	
G11375	HNBR5.0-35-125-P-NS-DAV	5.0	.035	125	DAV	
G11204	HNBR5.0-35-100-P-NS-FC3	5.0	.035	100	FC3	
G08421	HNBR5.0-35-100-P-NS-H1	5.0	.035	100	H1	
G08419	HNBR5.0-38-100-P-NS-H1	5.0	.038	100	H1	
G09899	HNBR5.0-38-100-P-NS-HN5	5.0	.038	100	HN5	
G11208	HNBR5.0-38-65-P-NS-JB1	5.0	.038	65	JB1	
G08472	HNBR5.0-35-100-P-NS-JB1	5.0	.035	100	JB1	
G08583	HNBR5.0-38-100-P-NS-JB1	5.0	.038	100	JB1	
G08809	HNBR5.0-35-100-P-NS-JB2	5.0	.035	100	JB2	
G09654	HNBR5.0-38-100-P-NS-JB2	5.0	.038	100	JB2	
G09751	HNBR5.0-35-40-P-NS-KMP	5.0	.035	40	KMP	
G09548	HNBR5.0-38-40-P-NS-KMP	5.0	.038	40	KMP	
G11458	HNBR5.0-35-65-P-NS-KMP	5.0	.035	65	KMP	
G09469	HNBR5.0-38-65-P-NS-KMP	5.0	.038	65	KMP	
G11457	HNBR5.0-38-100-P-NS-KMP	5.0	.038	100	KMP	
G11194	HNBR5.0-38-65-P-NS-LEV1	5.0	.038	65	LEV1	
G09312	HNBR5.0-38-80-P-NS-MIK	5.0	.038	80	MIK	
G11195	HNBR5.0-38-65-P-NS-MPA	5.0	.038	65	MPA	
G11467	HNBR5.0-38-80-P-NS-MPA	5.0	.038	80	MPA	
G11205	HNBR5.0-38-100-P-NS-MPA	5.0	.038	100	MPA	
G12154	HNBR5.0-38-125-P-NS-MPA	5.0	.038	125	MPA	
G11469	HNBR5.0-38-80-P-NS-MPB	5.0	.038	80	MPB	

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Service for details.

Cook Beacon® Tip 5.0 Fr






ANGIOGRAPHIC CATHETERS

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Tip Configuration	
G57017	HNBR5.0-35-90-P-NS-RBT	5.0	.035	90	RBT	
G08469	HNBR5.0-35-65-P-NS-RC1	5.0	.035	65	RC1	
G08641	HNBR5.0-38-65-P-NS-RC1	5.0	.038	65	RC1	
G08470	HNBR5.0-35-65-P-NS-RC2	5.0	.035	65	RC2	
G08642	HNBR5.0-38-65-P-NS-RC2	5.0	.038	65	RC2	
G08578	HNBR5.0-38-65-P-NS-RDC	5.0	.038	65	RDC	
G08444	HNBR5.0-35-65-P-NS-RIM	5.0	.035	65	RIM	
G10082	HNBR5.0-38-65-P-NS-RIM	5.0	.038	65	RIM	
G12870	HNBR5.0-38-100-P-NS-RIM	5.0	.038	100	RIM	
G09371	HNBR5.0-38-65-P-NS-RLG	5.0	.038	65	RLG	
G27853	HNBR5.0-38-80-P-NS-RLG	5.0	.038	80	RLG	
G11476	HNBR5.0-38-65-P-NS-SHK1.0	5.0	.038	65	SHK1.0	
G08677	HNBR5.0-38-65-P-NS-SIM1	5.0	.038	65	SIM1	
G08471	HNBR5.0-35-100-P-NS-SIM1	5.0	.035	100	SIM1	
G08584	HNBR5.0-38-100-P-NS-SIM1	5.0	.038	100	SIM1	
G08625	HNBR5.0-38-65-P-NS-SIM2	5.0	.038	65	SIM2	
G08422	HNBR5.0-35-100-P-NS-SIM2	5.0	.035	100	SIM2	
G08420	HNBR5.0-38-100-P-NS-SIM2	5.0	.038	100	SIM2	
G11517	HNBR5.0-38-125-P-NS-SIM2	5.0	.038	125	SIM2	
G08597	HNBR5.0-35-100-P-NS-SIM3	5.0	.035	100	SIM3	
G08585	HNBR5.0-38-100-P-NS-SIM3	5.0	.038	100	SIM3	
G11377	HNBR5.0-38-65-P-NS-TEGT	5.0	.038	65	TEGT	
G11193	HNBR5.0-38-100-P-NS-TEGT	5.0	.038	100	TEGT	
G31410	HNBR5.0-35-40-P-NS-VANSCHIE1	5.0	.035	40	VANSCHIE1	
G13795	HNBR5.0-35-65-P-NS-VANSCHIE1	5.0	.035	65	VANSCHIE1	
G35733	HNBR5.0-35-125-P-NS-VANSCHIE1	5.0	.035	125	VANSCHIE1	
G31409	HNBR5.0-35-40-P-NS-VANSCHIE2	5.0	.035	40	VANSCHIE2	
G13794	HNBR5.0-35-65-P-NS-VANSCHIE2	5.0	.035	65	VANSCHIE2	
G35734	HNBR5.0-35-125-P-NS-VANSCHIE2	5.0	.035	125	VANSCHIE2	
G31408	HNBR5.0-35-40-P-NS-VANSCHIE3	5.0	.035	40	VANSCHIE3	
G13792	HNBR5.0-35-65-P-NS-VANSCHIE3	5.0	.035	65	VANSCHIE3	
G35735	HNBR5.0-35-125-P-NS-VANSCHIE3	5.0	.035	125	VANSCHIE3	
G13783	HNBR5.0-35-65-P-NS-VANSCHIE4	5.0	.035	65	VANSCHIE4	
G35736	HNBR5.0-35-125-P-NS-VANSCHIE4	5.0	.035	125	VANSCHIE4	
G13793	HNBR5.0-35-65-P-NS-VANSCHIE5	5.0	.035	65	VANSCHIE5	
G35737	HNBR5.0-35-125-P-NS-VANSCHIE5	5.0	.035	125	VANSCHIE5	
G11484	HNBR5.0-38-100-P-NS-VERT	5.0	.038	100	VERT	
G12170	HNBR5.0-38-125-P-NS-VERT	5.0	.038	125	VERT	
G11209	HNBR5.0-38-80-P-NS-VS	5.0	.038	80	VS	

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Service for details.

Cook Beacon® Tip 5.0 Fr

ANGIOGRAPHIC CATHETERS

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Tip Configuration	
G11189	HNBR5.0-38-80-P-NS-VS1	5.0	.038	80	VS1	
G35974	HNBR5.0-35-125-P-NS-VS1	5.0	.035	125	VS1	
G11190	HNBR5.0-38-80-P-NS-VS2	5.0	.038	80	VS2	
G11191	HNBR5.0-38-80-P-NS-VS3	5.0	.038	80	VS3	
G27829	HNBR5.0-38-100-P-NS-VTK	5.0	.038	100	VTK	
G11642	HNBR5.0-38-125-P-NS-VTK	5.0	.038	125	VTK	
G08805	HNBR5.0-35-100-P-NS-WNBG	5.0	.035	100	WNBG	
G08582	HNBR5.0-38-100-P-NS-WNBG	5.0	.038	100	WNBG	

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Service for details.

Customer Service

EU Website: cookmedical.eu
 EDI: cookmedical.eu/edi
 Distributors: +353 61239240, ssc.distributors@cookmedical.com
 Austria: +43 179567121, oe.orders@cookmedical.com
 Belgium: +32 27001633, be.orders@cookmedical.com
 Denmark: +45 38487607, da.orders@cookmedical.com
 Finland: +358 972519996, fi.orders@cookmedical.com
 France: +33 171230269, fr.orders@cookmedical.com
 Germany: +49 6950072804, de.orders@cookmedical.com
 Hungary: +36 17779199, hu.orders@cookmedical.com
 Ireland: +353 61239252, ie.orders@cookmedical.com
 Italy: +39 0269682853, it.orders@cookmedical.com
 Netherlands: +31 202013367, nl.orders@cookmedical.com
 Norway: +47 23162968, no.orders@cookmedical.com
 Spain: +34 912702691, es.orders@cookmedical.com
 Sweden: +46 858769468, se.orders@cookmedical.com
 Switzerland - French: +41 448009609, fr.orders@cookmedical.com
 Switzerland - Italian: +41 448009609, it.orders@cookmedical.com
 Switzerland - German: +41 448009609, de.orders@cookmedical.com
 United Kingdom: +44 2073654183, uk.orders@cookmedical.com

USA Website: cookmedical.com

EDI: cookmedical.com/edi.do

Americas:

Phone: +1 812.339.2235, 800.457.4500, Fax: 800.554.8335

E-mail: orders@cookmedical.com

Australia:

Phone: +61 734346000, 1800777222, Fax: +61 734346001, 1800077283

E-mail: cau.custserv@cookmedical.com



AI, ESC, IR, OHNS, PI, RH, SUR-A4