

PUSHABILITY | TORQUEABILITY | VERSATILITY

# Performance you can feel



MORE THAN  
**100**  
TIP OPTIONS

**Torcon NB<sup>®</sup>**  
ADVANTAGE CATHETER



# Catheters: our evolving legacy

## 1960s

### 1963: Where it all started

Cook created and began producing catheters with radiopaque polyethylene tubing that allowed physicians to pre-form catheters to support interventional procedures.

### 1966: Tell us what curve you want

In the mid 1960s, Cook began offering physicians catheters with the sizes, lengths, and curves they needed for specific procedural needs. Our founder, Bill Cook, would say, "Tell us what curve you want," and sometimes the doctors would literally draw on a piece of paper what curve they wanted.

## 1990s

### 1990: Beacon® Tip Royal Flush® Plus Catheters

These nylon catheters offer enhanced radiopaque tips and continuous high flow rates with stability during injection.

### 1990: Torcon NB® Advantage Catheters

The Torcon features a soft, atraumatic tip and improved torque control.

## 2000s

### Beacon Tip Angiographic Catheters and Slip-Cath® Hydrophilic Angiographic Catheters

The stainless steel braiding and nylon tubing improves torque control, and the radiopaque Beacon tip technology provides enhanced tip visibility.


## Today

### The evolution continues

Over time, this core technology has evolved, and we now offer a large variety of catheter families that include a broad range of size, length, and curve options.

“At a medical trade show in 1964, Mr. Cook was using a Bunsen burner to demonstrate making catheters from plastic tubing when a man wandered by to ask if he could borrow the equipment, as the exhibit was closing for the day. He was Dr. Charles T. Dotter, who developed angioplasty, the technique of mechanically widening an obstructed blood vessel. He returned the next morning with 15 exquisitely made catheters, and Mr. Cook promptly sold them for \$10 apiece. They went on to form a mutually beneficial association in many projects over the years.”

Martin D. Bill Cook, medical device maker, dies at 80. New York Times Web site. <https://www.nytimes.com/2011/04/26/business/26cook.html>. Published April 25, 2011. Accessed July 12, 2023.



Multiple tip offerings

Nylon construction


**Torqueability and pushability**

Nylon construction with stainless steel braiding through the shaft provides control, pushability, and torque response.

**Versatility**

Lengths and curves to support various access sites and target anatomy

Stainless steel braiding




## Torcon NB®

ADVANTAGE CATHETER

### Order number key

**HNB4.1-35-125-P-2S-JB2-01**


















Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G46945	HNB4.1-35-100-P-NS-AL1-01	4.1	0.035	100	-		<b>AL1</b>
G46955	HNB4.1-35-80-P-NS-AR1-01	4.1	0.035	80	-		<b>AR1</b>
G58423	HNB4.1-35-80-P-NS-C2-01	4.1	0.035	80	-		<b>C2</b>
G46956	HNB4.1-35-80-P-NS-C3-01	4.1	0.035	80	-		<b>C3</b>
G46952	HNB4.1-35-125-P-2S-JB2-01	4.1	0.035	125	2		<b>JB2</b>
G46957	HNB4.1-35-80-P-NS-JIM-01	4.1	0.035	80	-		<b>JIM</b>
G46958	HNB4.1-35-80-P-NS-JL1-01	4.1	0.035	80	-		<b>JL1</b>
G46959	HNB4.1-35-80-P-NS-JL1.5-01	4.1	0.035	80	-		<b>JL1.5</b>
G46961	HNB4.1-35-80-P-NS-JL2-01	4.1	0.035	80	-		<b>JL2</b>
G46946	HNB4.1-35-100-P-NS-JL2-01	4.1	0.035	100	-		<b>JL2</b>
G46960	HNB4.1-35-80-P-NS-JL2.5-01	4.1	0.035	80	-		<b>JL2.5</b>
G46963	HNB4.1-35-80-P-NS-JL3-01	4.1	0.035	80	-		<b>JL3</b>
G46962	HNB4.1-35-80-P-NS-JL3.5-01	4.1	0.035	80	-		<b>JL3.5</b>
G46947	HNB4.1-35-100-P-NS-JL3.5-01	4.1	0.035	100	-		<b>JL3.5</b>
G46965	HNB4.1-35-80-P-NS-JR1-01	4.1	0.035	80	-		<b>JR1</b>
G46964	HNB4.1-35-80-P-NS-JR1.5-01	4.1	0.035	80	-		<b>JR1.5</b>
G46967	HNB4.1-35-80-P-NS-JR2-01	4.1	0.035	80	-		<b>JR2</b>
G46948	HNB4.1-35-100-P-NS-JR2-01	4.1	0.035	100	-		<b>JR2</b>
G46966	HNB4.1-35-80-P-NS-JR2.5-01	4.1	0.035	80	-		<b>JR2.5</b>
G46969	HNB4.1-35-80-P-NS-JR3-01	4.1	0.035	80	-		<b>JR3</b>

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G46968	HNB4.1-35-80-P-NS-JR3.5-01	4.1	0.035	80	-		JR3.5
G46949	HNB4.1-35-100-P-NS-JR3.5-01	4.1	0.035	100	-		JR3.5
G46970	HNB4.1-35-80-P-NS-JR4-01	4.1	0.035	80	-		JR4
G46950	HNB4.1-35-100-P-NS-JR4-01	4.1	0.035	100	-		JR4
G46973	HNB4.1-NT-65-P-NS-MPA-01	4.1	NT	65	-		MPA
G46944	HNB4.1-35-100-P-6S-NEFF-031793-01	4.1	0.035	100	6		NEFF-031793
G46954	HNB4.1-35-65-P-4S-NIH-01	4.1	0.035	65	4		NIH
G46971	HNB4.1-35-80-P-NS-NTR-01	4.1	0.035	80	-		NTR
G58422	HNB4.1-35-65-P-NS-RC1-01	4.1	0.035	65	-		RC1
G46972	HNB4.1-35-80-P-NS-SHK1.0-01	4.1	0.035	80	-		SHK1.0
G46951	HNB4.1-35-100-P-NS-SIM1-01	4.1	0.035	100	-		SIM1
G47148	HNB5.0-35-50-P-NS-0-01	5.0	0.035	50	-		0
G27677	HNB5.0-38-65-P-2S-0	5.0	0.038	65	2		0
G46990	HNB5.0-38-100-P-10S-0-01	5.0	0.038	100	10		0
G47160	HNB5.0-38-100-P-NS-0-01	5.0	0.038	100	-		0
G46995	HNB5.0-38-100-P-NS-AL1-01	5.0	0.038	100	-		AL1
G46996	HNB5.0-38-100-P-NS-AL2-01	5.0	0.038	100	-		AL2
G47035	HNB5.0-38-110-P-12S-AP2-01	5.0	0.038	110	12		AP2
G46997	HNB5.0-38-100-P-NS-AR1-01	5.0	0.038	100	-		AR1
G46998	HNB5.0-38-100-P-NS-AR2-01	5.0	0.038	100	-		AR2
G47079	HNB5.0-38-80-P-NS-BA-L-111182-01	5.0	0.038	80	-		BA-L-111182
G46980	HNB5.0-35-40-P-NS-BMC-01	5.0	0.035	40	-		BMC
G47043	HNB5.0-38-40-P-NS-BMC-01	5.0	0.038	40	-		BMC
G47051	HNB5.0-38-65-P-2S-C1-01	5.0	0.038	65	2		C1
G47055	HNB5.0-38-65-P-NS-C1-01	5.0	0.038	65	-		C1
G27698	HNB5.0-38-75-P-2S-C1	5.0	0.038	75	2		C1
G27702	HNB5.0-38-75-P-NS-C1	5.0	0.038	75	-		C1
G09875	HNB5.0-35-80-P-2S-C1	5.0	0.035	80	2		C1
G47081	HNB5.0-38-80-P-NS-C1-01	5.0	0.038	80	-		C1
G47130	HNB5.0-35-100-P-NS-C1-01	5.0	0.035	100	-		C1
G47161	HNB5.0-38-100-P-NS-C1-01	5.0	0.038	100	-		C1

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration		
G47052	HNB5.0-38-65-P-2S-C2-01	5.0	0.038	65	2		<b>C2</b>		
G47056	HNB5.0-38-65-P-NS-C2-01	5.0	0.038	65	-				
G27699	HNB5.0-38-75-P-2S-C2	5.0	0.038	75	2				
G06622	HNB5.0-35-80-P-2S-C2	5.0	0.035	80	2				
G47082	HNB5.0-38-80-P-NS-C2-01	5.0	0.038	80	-				
G46999	HNB5.0-38-100-P-NS-C2-01	5.0	0.038	100	-				
G47136	HNB5.0-35-125-P-NS-C2-01	5.0	0.035	125	-		<b>C3</b>		
G06828	HNB5.0-38-65-P-2S-C3	5.0	0.038	65	2				
G05999	HNB5.0-38-65-P-NS-C3	5.0	0.038	65	-				
G09521	HNB5.0-38-80-P-NS-C3	5.0	0.038	80	-		<b>CANADA-041480</b>		
G47131	HNB5.0-35-100-P-NS-CANADA-041480-01	5.0	0.035	100	-				
G47217	HNB5.0-38-80-P-NS-CHG2.5-01	5.0	0.038	80	-				<b>CHG2.5</b>
G27640	HNB5.0-35-75-P-NS-CHG-B	5.0	0.035	75	-				
G47074	HNB5.0-38-75-P-NS-CHG-B-01	5.0	0.038	75	-		<b>CHG-B</b>		
G47084	HNB5.0-38-80-P-NS-CHG-C-01	5.0	0.038	80	-				<b>CHG-C</b>
G47162	HNB5.0-38-100-P-NS-CK1-01	5.0	0.038	100	-				
G46982	HNB5.0-35-65-P-1S-COLAPINTO-1-01	5.0	0.035	65	1		<b>COLAPINTO-1</b>		
G47137	HNB5.0-35-125-P-NS-C-PS-01	5.0	0.035	125	-				<b>C-PS</b>
G47182	HNB5.0-38-65-P-NS-DAV-01	5.0	0.038	65	-		<b>DAV</b>		
G47000	HNB5.0-38-100-P-NS-DAV-01	5.0	0.038	100	-				
G47172	HNB5.0-38-125-P-NS-DAV-01	5.0	0.038	125	-				<b>EKISAI-111984</b>
G10796	HNB5.0-38-80-P-NS-EKISAI-111984	5.0	0.038	80	-		<b>FC3</b>		
G47132	HNB5.0-35-100-P-NS-FC3-01	5.0	0.035	100	-				<b>FINCK-101979</b>
G47183	HNB5.0-38-65-P-NS-FINCK-101979-01	5.0	0.038	65	-				
G46976	HNB5.0-35-100-P-NS-H1-01	5.0	0.035	100	-		<b>H1</b>		
G06607	HNB5.0-38-65-P-NS-H1	5.0	0.038	65	-				
G47001	HNB5.0-38-100-P-NS-H1-01	5.0	0.038	100	-				<b>H3</b>
G47173	HNB5.0-38-125-P-NS-H1-01	5.0	0.038	125	-		<b>HET</b>		
G58425	HNB5.0-38-100-P-NS-H3-01	5.0	0.038	100	-				
G32167	HNB5.0-NT-65-P-NS-HET	5.0	NT	65	-				

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.
















Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G47002	HNB5.0-38-100-P-NS-HIGA-A-100380-01	5.0	0.038	100	-		HIGA-A-100380
G47163	HNB5.0-38-100-P-NS-HN1-01	5.0	0.038	100	-		HN1
G47003	HNB5.0-38-100-P-NS-HN2-01	5.0	0.038	100	-		HN2
G47174	HNB5.0-38-125-P-NS-HN2-01	5.0	0.038	125	-		HN2
G47004	HNB5.0-38-100-P-NS-HN3-01	5.0	0.038	100	-		HN3
G47005	HNB5.0-38-100-P-NS-HN4-01	5.0	0.038	100	-		HN4
G47006	HNB5.0-38-100-P-NS-HN5-01	5.0	0.038	100	-		HN5
G47175	HNB5.0-38-125-P-NS-HN5-01	5.0	0.038	125	-		HN5
G47133	HNB5.0-35-100-P-NS-HNK1-01	5.0	0.035	100	-		HNK1
G10599	HNB5.0-38-80-P-NS-HS1	5.0	0.038	80	-		HS1
G10598	HNB5.0-38-80-P-NS-HS2	5.0	0.038	80	-		HS2
G47184	HNB5.0-38-65-P-NS-JB1-01	5.0	0.038	65	-		JB1
G47007	HNB5.0-38-100-P-NS-JB1-01	5.0	0.038	100	-		JB1
G47176	HNB5.0-38-125-P-NS-JB1-01	5.0	0.038	125	-		JB1
G46977	HNB5.0-35-100-P-NS-JB2-01	5.0	0.035	100	-		JB2
G47008	HNB5.0-38-100-P-NS-JB2-01	5.0	0.038	100	-		JB2
G47040	HNB5.0-38-125-P-NS-JB2-01	5.0	0.038	125	-		JB2
G47009	HNB5.0-38-100-P-NS-JB3-01	5.0	0.038	100	-		JB3
G47010	HNB5.0-38-100-P-NS-JIM-01	5.0	0.038	100	-		JIM
G47012	HNB5.0-38-100-P-NS-JL2-01	5.0	0.038	100	-		JL2
G10742	HNB5.0-38-80-P-NS-JL2.5	5.0	0.038	80	-		JL2.5
G47011	HNB5.0-38-100-P-NS-JL2.5-01	5.0	0.038	100	-		JL2.5
G09872	HNB5.0-38-80-P-NS-JL3	5.0	0.038	80	-		JL3
G47014	HNB5.0-38-100-P-NS-JL3-01	5.0	0.038	100	-		JL3
G47013	HNB5.0-38-100-P-NS-JL3.5-01	5.0	0.038	100	-		JL3.5
G47128	HNB5.0-38-100-P-NS-JL4-01	5.0	0.038	100	-		JL4
G47015	HNB5.0-38-100-P-NS-JL4.5-01	5.0	0.038	100	-		JL4.5

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.

















Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G47017	HNB5.0-38-100-P-NS-JL5-01	5.0	0.038	100	-		<b>JL5</b>
G30163	HNB5.0-38-80-P-NS-JR1.5	5.0	0.038	80	-		<b>JR1.5</b>
G10733	HNB5.0-38-80-P-NS-JR2	5.0	0.038	80	-		<b>JR2</b>
G46979	HNB5.0-35-100-P-NS-JR2-01	5.0	0.035	100	-		<b>JR2</b>
G47018	HNB5.0-38-100-P-NS-JR2-01	5.0	0.038	100	-		<b>JR2</b>
G08985	HNB5.0-38-80-P-NS-JR2.5	5.0	0.038	80	-		<b>JR2.5</b>
G46978	HNB5.0-35-100-P-NS-JR2.5-01	5.0	0.035	100	-		<b>JR2.5</b>
G10757	HNB5.0-38-80-P-NS-JR3	5.0	0.038	80	-		<b>JR3</b>
G47020	HNB5.0-38-100-P-NS-JR3-01	5.0	0.038	100	-		<b>JR3</b>
G47019	HNB5.0-38-100-P-NS-JR3.5-01	5.0	0.038	100	-		<b>JR3.5</b>
G47021	HNB5.0-38-100-P-NS-JR4-01	5.0	0.038	100	-		<b>JR4</b>
G47041	HNB5.0-38-125-P-NS-JR4-01	5.0	0.038	125	-		<b>JR4</b>
G47022	HNB5.0-38-100-P-NS-JR5-01	5.0	0.038	100	-		<b>JR5</b>
G47044	HNB5.0-38-40-P-NS-KMP-01	5.0	0.038	40	-		<b>KMP</b>
G47150	HNB5.0-35-65-P-NS-KMP-01	5.0	0.035	65	-		<b>KMP</b>
G47185	HNB5.0-38-65-P-NS-KMP-01	5.0	0.038	65	-		<b>KMP</b>
G47164	HNB5.0-38-100-P-NS-KMP-01	5.0	0.038	100	-		<b>KMP</b>
G47186	HNB5.0-38-65-P-NS-LEV1-01	5.0	0.038	65	-		<b>LEV1</b>
G47165	HNB5.0-38-100-P-NS-MAN-01	5.0	0.038	100	-		<b>MAN</b>
G10910	HNB5.0-38-80-P-NS-MAYO-A-041994	5.0	0.038	80	-		<b>MAYO-A-041994</b>
G47095	HNB5.0-38-80-P-NS-MIK-01	5.0	0.038	80	-		<b>MIK</b>
G47134	HNB5.0-35-100-P-NS-MIK-01	5.0	0.035	100	-		<b>MIK</b>
G30275	HNB5.0-38-65-P-1S-MK1B	5.0	0.038	65	1		<b>MK1B</b>
G47059	HNB5.0-38-65-P-NS-MPA-01	5.0	0.038	65	-		<b>MPA</b>
G47108	HNB5.0-NT-65-P-NS-MPA-01	5.0	NT	65	-		<b>MPA</b>
G47209	HNB5.0-38-80-P-NS-MPA-01	5.0	0.038	80	-		<b>MPA</b>
G46992	HNB5.0-38-100-P-2S-MPA-01	5.0	0.038	100	2		<b>MPA</b>
G46994	HNB5.0-38-100-P-6S-MPA-01	5.0	0.038	100	6		<b>MPA</b>
G47023	HNB5.0-38-100-P-NS-MPA-01	5.0	0.038	100	-		<b>MPA</b>
G47106	HNB5.0-NT-100-P-NS-MPA-01	5.0	NT	100	-		<b>MPA</b>
G47177	HNB5.0-38-125-P-NS-MPA-01	5.0	0.038	125	-		<b>MPA</b>

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.



Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G06282	HNB5.0-35-80-P-NS-MPB	5.0	0.035	80	-		
G47096	HNB5.0-38-80-P-NS-MPB-01	5.0	0.038	80	-		<b>MPB</b>
G47024	HNB5.0-38-100-P-NS-MPB-01	5.0	0.038	100	-		
G47078	HNB5.0-38-80-P-8S-NEFF-01	5.0	0.038	80	8		<b>NEFF</b>
G46975	HNB5.0-35-100-P-8S-NEFF-01	5.0	0.035	100	8		
G47077	HNB5.0-38-80-P-6S-NEFF-042695-01	5.0	0.038	80	6		<b>NEFF-042695</b>
G46993	HNB5.0-38-100-P-4S-NIH-01	5.0	0.038	100	4		<b>NIH</b>
G47036	HNB5.0-38-110-P-12S-PED-01	5.0	0.038	110	12		<b>PED</b>
G47025	HNB5.0-38-100-P-NS-PICARD-01	5.0	0.038	100	-		<b>PICARD</b>
G46974	HNB5.0-35-100-P-10S-PIG-01	5.0	0.035	100	10		
G46991	HNB5.0-38-100-P-10S-PIG-01	5.0	0.038	100	10		<b>PIG</b>
G47037	HNB5.0-38-110-P-12S-PIG-01	5.0	0.038	110	12		
G47039	HNB5.0-38-110-P-6S-PIG-01	5.0	0.038	110	6		
G47038	HNB5.0-38-110-P-12S-PIG-PS-01	5.0	0.038	110	12		<b>PIG-PS</b>
G47151	HNB5.0-35-65-P-NS-RBT-01	5.0	0.035	65	-		<b>RBT</b>
G47060	HNB5.0-38-65-P-NS-RC1-01	5.0	0.038	65	-		<b>RC1</b>
G47045	HNB5.0-38-40-P-NS-RC2-01	5.0	0.038	40	-		
G11433	HNB5.0-38-65-P-2S-RC2	5.0	0.038	65	2		<b>RC2</b>
G47061	HNB5.0-38-65-P-NS-RC2-01	5.0	0.038	65	-		
G47062	HNB5.0-38-65-P-NS-RDC-01	5.0	0.038	65	-		<b>RDC</b>
G47166	HNB5.0-38-100-P-NS-RDC-01	5.0	0.038	100	-		
G58424	HNB5.0-38-65-P-NS-RH-01	5.0	0.038	65	-		
G47075	HNB5.0-38-75-P-NS-RH-01	5.0	0.038	75	-		<b>RH</b>
G47099	HNB5.0-38-80-P-NS-RH-01	5.0	0.038	80	-		
G47076	HNB5.0-38-75-P-NS-RHR-01	5.0	0.038	75	-		<b>RHR</b>
G46983	HNB5.0-35-65-P-6S-RIM-01	5.0	0.035	65	6		
G47063	HNB5.0-38-65-P-NS-RIM-01	5.0	0.038	65	-		<b>RIM</b>
G47100	HNB5.0-38-80-P-NS-RIM-01	5.0	0.038	80	-		
G47167	HNB5.0-38-100-P-NS-RIM-01	5.0	0.038	100	-		

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G47046	HNB5.0-38-40-P-NS-RLG-01	5.0	0.038	40	-		
G47064	HNB5.0-38-65-P-NS-RLG-01	5.0	0.038	65	-		<b>RLG</b>
G47101	HNB5.0-38-80-P-NS-RLG-01	5.0	0.038	80	-		
G47102	HNB5.0-38-80-P-NS-RS-01	5.0	0.038	80	-		<b>RS</b>
G47168	HNB5.0-38-100-P-NS-SHETTY-050181-01	5.0	0.038	100	-		<b>SHETTY-050181</b>
G47066	HNB5.0-38-65-P-NS-SHK1.0-01	5.0	0.038	65	-		
G27689	HNB5.0-38-70-P-NS-SHK1.0	5.0	0.038	70	-		<b>SHK1.0</b>
G47190	HNB5.0-38-65-P-NS-SIM1-01	5.0	0.038	65	-		
G47026	HNB5.0-38-100-P-NS-SIM1-01	5.0	0.038	100	-		<b>SIM1</b>
G47178	HNB5.0-38-125-P-NS-SIM1-01	5.0	0.038	125	-		
G47067	HNB5.0-38-65-P-NS-SIM2-01	5.0	0.038	65	-		
G47027	HNB5.0-38-100-P-NS-SIM2-01	5.0	0.038	100	-		<b>SIM2</b>
G47179	HNB5.0-38-125-P-NS-SIM2-01	5.0	0.038	125	-		
G47028	HNB5.0-38-100-P-NS-SIM3-01	5.0	0.038	100	-		<b>SIM3</b>
G47029	HNB5.0-38-100-P-NS-SIM4-01	5.0	0.038	100	-		<b>SIM4</b>
G47030	HNB5.0-38-100-P-NS-SPENCER-2-101772-01	5.0	0.038	100	-		<b>SPENCER-2-101772</b>
G47192	HNB5.0-38-65-P-NS-TC-01	5.0	0.038	65	-		<b>TC</b>
G47193	HNB5.0-38-65-P-NS-TC-BNK-01	5.0	0.038	65	-		<b>TC-BNK</b>
G47181	HNB5.0-38-40-P-NS-TEGT-01	5.0	0.038	40	-		
G47194	HNB5.0-38-65-P-NS-TEGT-01	5.0	0.038	65	-		<b>TEGT</b>
G47169	HNB5.0-38-100-P-NS-TEGT-01	5.0	0.038	100	-		
G12783	HNB5.0-38-65-P-1S-VA-070793	5.0	0.038	65	1		<b>VA-070793</b>
G47031	HNB5.0-38-100-P-NS-VAL-01	5.0	0.038	100	-		<b>VAL</b>
G47145	HNB5.0-35-40-P-NS-VANSCHIE1-01	5.0	0.035	40	-		
G47152	HNB5.0-35-65-P-NS-VANSCHIE1-01	5.0	0.035	65	-		<b>VANSCHIE1</b>
G47139	HNB5.0-35-125-P-NS-VANSCHIE1-01	5.0	0.035	125	-		
G47146	HNB5.0-35-40-P-NS-VANSCHIE2-01	5.0	0.035	40	-		
G47153	HNB5.0-35-65-P-NS-VANSCHIE2-01	5.0	0.035	65	-		<b>VANSCHIE2</b>
G47140	HNB5.0-35-125-P-NS-VANSCHIE2-01	5.0	0.035	125	-		

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.

Order Number	Reference Part Number	Fr	Accepts Wire Guide Diameter inch	Length cm	Number of Sideports	Tip Configuration Image	Tip Configuration
G47147	HNB5.0-35-40-P-NS-VANSCHIE3-01	5.0	0.035	40	-		
G47154	HNB5.0-35-65-P-NS-VANSCHIE3-01	5.0	0.035	65	-		<b>VANSCHIE3</b>
G47141	HNB5.0-35-125-P-NS-VANSCHIE3-01	5.0	0.035	125	-		
G47155	HNB5.0-35-65-P-NS-VANSCHIE4-01	5.0	0.035	65	-		<b>VANSCHIE4</b>
G47142	HNB5.0-35-125-P-NS-VANSCHIE4-01	5.0	0.035	125	-		
G47156	HNB5.0-35-65-P-NS-VANSCHIE5-01	5.0	0.035	65	-		<b>VANSCHIE5</b>
G47143	HNB5.0-35-125-P-NS-VANSCHIE5-01	5.0	0.035	125	-		
G47032	HNB5.0-38-100-P-NS-VERT-01	5.0	0.038	100	-		<b>VERT</b>
G47180	HNB5.0-38-125-P-NS-VERT-01	5.0	0.038	125	-		
G47211	HNB5.0-38-80-P-NS-VS-01	5.0	0.038	80	-		<b>VS</b>
G47212	HNB5.0-38-80-P-NS-VS1-01	5.0	0.038	80	-		<b>VS1</b>
G47144	HNB5.0-35-125-P-NS-VS1-01	5.0	0.035	125	-		
G47213	HNB5.0-38-80-P-NS-VS2-01	5.0	0.038	80	-		<b>VS2</b>
G47170	HNB5.0-38-100-P-NS-VS2-01	5.0	0.038	100	-		
G47214	HNB5.0-38-80-P-NS-VS3-01	5.0	0.038	80	-		<b>VS3</b>
G47171	HNB5.0-38-100-P-NS-VS3-01	5.0	0.038	100	-		
G47033	HNB5.0-38-100-P-NS-VTK-01	5.0	0.038	100	-		<b>VTK</b>
G47042	HNB5.0-38-125-P-NS-VTK-01	5.0	0.038	125	-		
G47135	HNB5.0-35-100-P-NS-WAIKATO-01	5.0	0.035	100	-		<b>WAIKATO</b>
G47034	HNB5.0-38-100-P-NS-WNBG-01	5.0	0.038	100	-		<b>WNBG</b>
G47254	HNB6.0-38-40-P-NS-BMC-01	6.0	0.038	40	-		<b>BMC</b>
G47256	HNB6.0-38-65-P-NS-BMC-01	6.0	0.038	65	-		
G47238	HNB6.0-38-100-P-NS-JL4-01	6.0	0.038	100	-		<b>JL4</b>
G47241	HNB6.0-38-100-P-NS-JR4-01	6.0	0.038	100	-		<b>JR4</b>
G47263	HNB6.0-NT-100-P-NS-JR4-01	6.0	NT	100	-		
G47124	HNB7.0-38-35-P-NS-KMP-01	7.0	0.038	35	-		<b>KMP</b>
G47110	HNB7.0-38-100-P-10S-MPA-01	7.0	0.038	100	10		
G47120	HNB7.0-38-100-P-NS-MPA-01	7.0	0.038	100	-		<b>MPA</b>
G47127	HNB7.0-NT-100-P-NS-MPA-01	7.0	NT	100	-		
G47125	HNB7.0-38-65-P-NS-VERT-01	7.0	0.038	65	-		<b>VERT</b>
G47123	HNB7.0-38-110-P-NS-VERT-01	7.0	0.038	110	-		

Some products or part numbers may not be available in all markets. Contact your local Cook representative or Customer Support & Distribution for details.



Scan this code  
for more information on  
Torcon NB Advantage Catheter

### Customer Service

EU Website: [cookmedical.eu](http://cookmedical.eu)  
EDI: [cookmedical.eu/edi](http://cookmedical.eu/edi)  
Distributors: +353 61239240, [ssc.distributors@cookmedical.com](mailto:ssc.distributors@cookmedical.com)  
Austria: +43 179567121, [oe.orders@cookmedical.com](mailto:oe.orders@cookmedical.com)  
Belgium: +32 27001702, [be.orders@cookmedical.com](mailto:be.orders@cookmedical.com)  
Denmark: +45 38487607, [da.orders@cookmedical.com](mailto:da.orders@cookmedical.com)  
Finland: +358 972519996, [fi.orders@cookmedical.com](mailto:fi.orders@cookmedical.com)  
France: +33 171230269, [fr.orders@cookmedical.com](mailto:fr.orders@cookmedical.com)  
Germany: +49 6950072804, [de.orders@cookmedical.com](mailto:de.orders@cookmedical.com)  
Hungary: +36 17779199, [hu.orders@cookmedical.com](mailto:hu.orders@cookmedical.com)  
Iceland: +354 8007615, [IS.orders@cookmedical.com](mailto:IS.orders@cookmedical.com)  
Ireland: +353 61239252, [ie.orders@cookmedical.com](mailto:ie.orders@cookmedical.com)  
Italy: +39 0269682853, [it.orders@cookmedical.com](mailto:it.orders@cookmedical.com)  
Netherlands: +31 202013367, [nl.orders@cookmedical.com](mailto:nl.orders@cookmedical.com)  
Norway: +47 23162968, [no.orders@cookmedical.com](mailto:no.orders@cookmedical.com)  
Spain: +34 912702691, [es.orders@cookmedical.com](mailto:es.orders@cookmedical.com)  
Sweden: +46 858769468, [se.orders@cookmedical.com](mailto:se.orders@cookmedical.com)  
Switzerland - French: +41 448009609, [fr.orders@cookmedical.com](mailto:fr.orders@cookmedical.com)  
Switzerland - Italian: +41 448009609, [it.orders@cookmedical.com](mailto:it.orders@cookmedical.com)  
Switzerland - German: +41 448009609, [de.orders@cookmedical.com](mailto:de.orders@cookmedical.com)  
United Kingdom: +44 2073654183, [uk.orders@cookmedical.com](mailto:uk.orders@cookmedical.com)

USA Website: [cookmedical.com](http://cookmedical.com)

EDI: [cookmedical.com/edi.do](http://cookmedical.com/edi.do)

#### Americas:

Phone: +1 812.339.2235, 800.457.4500, Fax: 800.554.8335

E-mail: [customersupport@cookmedical.com](mailto:customersupport@cookmedical.com)

#### Australia:

Phone: +61 734346000, 1800777222, Fax: +61 734346001, 1800077283

E-mail: [cau.custserv@cookmedical.com](mailto:cau.custserv@cookmedical.com)



AI, ESC, IR, OHNS, PI, RH, SUR-8.5X11